



Fig. 33- Color-infrared aerial photograph showing vegetation-free scars (light-tone) of recent and historical debris flows. Route 411 is in the lower left (USGS NAPP 10716-5, acquired 4-02-1998).