

PHOTO SUMMARY

Site Name: Two Medicine River at US-89 near Browning, MT

Site ID: 026

Photos By: R. Fosness

Date: 09/12/2016



Photo #001

**1 channel-width
U/S of bridge**

**Upstream
left bank**

Comments:



Photo #002

**1 channel-width
U/S of bridge**

**Upstream looking
D/S at bridge**

Comments:

PHOTO SUMMARY

Site Name: Two Medicine River at US-89 near Browning, MT

Site ID: 026

Photos By: R. Fosness

Date: 09/12/2016



Photo #003

**Immediately
U/S of bridge**

**Upstream
left bank**

Comments:



Photo #004

**On/Under
bridge**

**On/Under bridge
looking U/S**

Comments:

PHOTO SUMMARY

Site Name: Two Medicine River at US-89 near Browning, MT

Site ID: 026

Photos By: R. Fosness

Date: 09/12/2016



Photo #005

**On/Under
bridge**

**On/Under bridge
looking D/S**

Comments:



Photo #006

Substructure

**Representative
pier/bent**

Comments:
Debris present at
U/S of pier 2

PHOTO SUMMARY

Site Name: Two Medicine River at US-89 near Browning, MT

Site ID: 026

Photos By: R. Fosness

Date: 09/12/2016



Photo #007

**Immediately
D/S of bridge**

**Downstream
right bank**

Comments:



Photo #008

**1 channel-width
D/S of bridge**

**Downstream
left bank**

Comments:

PHOTO SUMMARY

Site Name: Two Medicine River at US-89 near Browning, MT

Site ID: 026

Photos By: R. Fosness

Date: 09/12/2016



Photo #009

**1 channel-width
D/S of bridge**

**Downstream
right bank**

Comments:



Photo #010

Soil material

Bank material

Comments:

PHOTO SUMMARY

Site Name: Two Medicine River at US-89 near Browning, MT

Site ID: 026

Photos By: R. Fosness

Date: 09/12/2016



Photo #011

Other

Comments:
Countermeasures
visible at pier 3