



EXPLANATION

- | | | | | | | | |
|--|--|--|------------------------|--|--|--|--|
| | Lithologic correlation based on geophysical logs | | Acoustic televiwer log | | Gamma log, intensity increases to right | | Coal bed interpreted from density log |
| | Reported bottom of overburden, dashed where approximate | | Optical televiwer log | | Single-point resistance log, resistance increases to right | | Well nest or cluster, with identifier; screen interval identifier in italics |
| | Fault, inferred; arrows show direction of displacement; ? indicates uncertainty of location and movement | | | | Density log, density increases to right | | Screened or open interval |

Section C-C' with geophysical log correlations, Valmont TCE Superfund Site, Luzerne County, Pennsylvania

By
Lisa A. Senior, Alex R. Fiore, and Philip H. Bird
2021