


Photographs by Air Photo Tech, Anchorage

INTERIOR—GEOLOGICAL SURVEY, WASHINGTON, D.C.—1969—G69100



**MAP AND PHOTOGRAPH OF GROUND CRACKING ON THE
KNIK-MATANUSKA RIVER FLOOD PLAIN, ALASKA**