



EXPLANATION

- Toe of steep bedrock valley wall
- Edge of avalanche debris
- Flooded area
- Water-filled channel
- Ground cracks
- 35.8
Railroad
(Bridges indicated by mile)
- Drainage-diversion dike

Mapping from Aerial photographs taken by
Air Photo Tech. Inc., Anchorage

MAP OF GROUND CRACKING, FLOODING, AND AVALANCHES ON HUNTER FLATS, ALASKA,
THAT RESULTED FROM THE MARCH 27 EARTHQUAKE

