









Photographs from U. S. Army Mohawk



Photographs by Air Photo Tech, Anchorage



INTERIOR—GEOLOGICAL SURVEY, WASHINGTON, D. C.—1988—545D

MAPS AND AERIAL PHOTOGRAPHS OF GROUND CRACKING IN THE PORTAGE AREA, ALASKA,
THAT RESULTED FROM THE MARCH 27 EARTHQUAKE