FIGURE 1.–LOCATIONS OF SITES 1–4, 20–27, AND 30–38



FIGURE 2.–LOCATIONS OF SITES 5–19, 26, AND 28–29. SEE FIGURE 1 FOR LOCATION

MAPS SHOWING SITES OF LIQUEFACTION, GROUND FAILURE, AND OTHER SECONDARY GROUND EFFECTS CAUSED BY THE 1979 IMPERIAL VALLEY EARTHQUAKE, CALIFORNIA