

PEACE RIVER BASIN

20. 02296260 CHARLIE CREEK NEAR CREWSVILLE, FL

LOCATION.--Lat 27°27'33", long 81°40'43", in SE¹/₄ sec.2, T.35 S., R.26 E., Hardee County, Hydrologic Unit 03100101, at bridge on State Highway 66, 7.1 miles west of Crewsville, and 14.5 miles upstream from mouth.

CONTRIBUTING DRAINAGE AREA.--142 mi².

DATUM OF GAGE.--Not determined.

Date	Discharge (cubic foot per second)	Gage height (feet)	Date	Discharge (cubic foot per second)	Gage height (feet)
1981-02-09	200	13.85	1992-06-28	425	16.85
1982-06-21	4,000	20.72	1993-04-01	565	17.72
1983-02-18	2,800	20.01	1994-09-19	2,260	19.61
1984-07-21	582	16.62	1994-10-05	2,240	19.60
1985-09-07	470	16.77	1995-10-11	640	18.00
1986-08-07	290	15.41	1997-09-08	550	17.65
1987-03-31	1,100	18.49	1998-03-21	6,840	21.34
1988-09-08	2,990	20.16	1999-08-06	705	18.11
1989-09-03	337	15.98	1999-10-10	2,770	19.97
1990-08-20	1,610	19.26	2001-09-14	5,420	20.95
1991-08-27	795	18.25			

EXPLANATION OF PEAK DATA CODES

Discharge Qualification Codes	Gage Height Qualification Codes
¹ Discharge is a maximum daily average. ² Discharge is an estimate. ³ Discharge affected by dam failure. ⁴ Discharge less than indicated value, which is minimum recordable discharge at this site. ⁵ Discharge affected to unknown degree by regulation or diversion. ⁶ Discharge affected by regulation or diversion. ⁷ Discharge is an historic peak. ^B Month or day of occurrence is unknown or not exact. ^E Only annual maximum peak available for this year. ^M Missing value.	¹ Gage height affected by backwater. ² Gage height not the maximum for the year. ³ Gage height at different site and/or datum. ⁴ Gage height below minimum recordable elevation. ⁵ Gage height is an estimate. ⁶ Gage datum changed during this year. ^M Missing value.