

HILLSBOROUGH RIVER BASIN**53. 02301800 SIXMILE CREEK AT TAMPA, FL**

LOCATION.--Lat 27°57'59", long 82°22'07", in NW¹/₄ sec.13, T.29 S., R.19 E., Hillsborough County, Hydrologic Unit 03100206, near right bank on upstream side of bridge on State Highway 574, at southeastern city limits of Tampa, and 4.0 miles upstream from mouth.

CONTRIBUTING DRAINAGE AREA.--28 mi².

DATUM OF GAGE.-- NGVD 1929.

Date	Discharge (cubic foot per second)	Gage height (feet)	Date	Discharge (cubic foot per second)	Gage height (feet)
1957-08-06	402	7.73	1966-07-13	464	8.04
1958-02-26	822	9.18	1966-10-09	660	9.02
1959-08-29	1,150	9.92	1968-09-13	939	10.19
1960-09-11	1,290	11.47	1969-09-21	736	9.34
1961-08-28	147	5.60	1969-12-10	726	9.30
1962-08-25	842	9.77	1971-09-10	410	10.10
1963-02-12	496	8.23	1972-06-19	186	8.80
1964-01-12	779	9.52	1973-09-17	270	11.06
1965-07-31	806	9.63	1974-06-27	567	11.73

EXPLANATION OF PEAK DATA CODES

Discharge Qualification Codes	Gage Height Qualification Codes
¹ Discharge is a maximum daily average. ² Discharge is an estimate. ³ Discharge affected by dam failure. ⁴ Discharge less than indicated value, which is minimum recordable discharge at this site. ⁵ Discharge affected to unknown degree by regulation or diversion. ⁶ Discharge affected by regulation or diversion. ⁷ Discharge is an historic peak. ^B Month or day of occurrence is unknown or not exact. ^E Only annual maximum peak available for this year. ^M Missing value.	¹ Gage height affected by backwater. ² Gage height not the maximum for the year. ³ Gage height at different site and/or datum. ⁴ Gage height below minimum recordable elevation. ⁵ Gage height is an estimate. ⁶ Gage datum changed during this year. ^M Missing value.