

TAMPA BAY AND COASTAL AREAS

64. 02306774 ROCKY CREEK AT STATE HIGHWAY 587 NEAR CITRUS PARK, FL

LOCATION.--Lat 28°03'55", long 82°34'00", in NW¹/₄ sec.12, T.28 S., R.17 E., Hillsborough County, Hydrologic Unit 03100206, on right bank 20 ft north of bridge on State Highway 587 (Gunn Highway), 0.2 mi east of intersection Sheldon Road and Gunn Highway, 1.2 mi south of Citrus Park, and 9.0 mi upstream from mouth.

CONTRIBUTING DRAINAGE AREA.--17.8 mi².

DATUM OF GAGE.-- NGVD 1929.

Date	Discharge (cubic foot per second)	Gage height (feet)	Date	Discharge (cubic foot per second)	Gage height (feet)
1986-07-30	125	21.66	1994-08-28	79.0	20.55
1987-03-31	223	23.83	1995-06-25	118	22.37
1988-09-09	360	25.24	1995-10-19	166	22.20
1988-11-23	345	25.05	1997-09-27	157	23.70
1990-07-19	88.0	20.71	1997-12-27	366	25.52
1991-08-01	313	24.63	1999-09-28	52 ^E	20.05
1992-08-30	74.0	20.42	2000-09-20	143	21.96
1992-10-04	106	21.20	2001-09-15	247	23.28

EXPLANATION OF PEAK DATA CODES

Discharge Qualification Codes	Gage Height Qualification Codes
¹ Discharge is a maximum daily average. ² Discharge is an estimate. ³ Discharge affected by dam failure. ⁴ Discharge less than indicated value, which is minimum recordable discharge at this site. ⁵ Discharge affected to unknown degree by regulation or diversion. ⁶ Discharge affected by regulation or diversion. ⁷ Discharge is an historic peak. ^B Month or day of occurrence is unknown or not exact. ^E Only annual maximum peak available for this year. ^M Missing value.	¹ Gage height affected by backwater. ² Gage height not the maximum for the year. ³ Gage height at different site and/or datum. ⁴ Gage height below minimum recordable elevation. ⁵ Gage height is an estimate. ⁶ Gage datum changed during this year. ^M Missing value.