

COASTAL AREA FROM TAMPA BAY TO WITHLACOOCHEE RIVER

70. 02309980 ANCLOTE RIVER NEAR ODESSA, FL

LOCATION.--Lat 28°13'17", long 82°38'07", in SE¹/₄ sec.18, T.26 S., R.17 E., Pasco County, Hydrologic Unit 03100207, on left bank, 30 ft downstream from wooden bridge on private road, 3.2 mi northwest of Odessa, and 18 mi upstream from mouth.

CONTRIBUTING DRAINAGE AREA.--68.1 mi².

DATUM OF GAGE.-- NGVD 1929.

Date	Discharge (cubic foot per second)	Gage height (feet)	Date	Discharge (cubic foot per second)	Gage height (feet)
1981-08-02	712	27.87	1988-11-24	999	28.56
1983-12-31	569	27.45	1990-07-16	456	27.06
1985-09-02	1,060	29.51	1991-07-15	712	27.87
1986-01-12	935	29.05	1992-09-10	260 ²	M
1987-03-31	2,270	30.38	1992-10-04	823	28.16
1988-09-09	2,800	30.98	1994-09-18	375	26.56

EXPLANATION OF PEAK DATA CODES

Discharge Qualification Codes	Gage Height Qualification Codes
¹ Discharge is a maximum daily average. ² Discharge is an estimate. ³ Discharge affected by dam failure. ⁴ Discharge less than indicated value, which is minimum recordable discharge at this site. ⁵ Discharge affected to unknown degree by regulation or diversion. ⁶ Discharge affected by regulation or diversion. ⁷ Discharge is an historic peak. ^B Month or day of occurrence is unknown or not exact. ^E Only annual maximum peak available for this year. ^M Missing value.	¹ Gage height affected by backwater. ² Gage height not the maximum for the year. ³ Gage height at different site and/or datum. ⁴ Gage height below minimum recordable elevation. ⁵ Gage height is an estimate. ⁶ Gage datum changed during this year. ^M Missing value.