

WITHLACOCHEE RIVER BASIN

85. 02312690 CHITTY CHATTY CREEK NEAR WILDWOOD, FL

LOCATION.--Lat 28°48'33", long 81°58'59", in NW¹/₄ sec. 26, T. 19 S., R. 23 E., Sumter County, Hydrologic Unit 03100208, near center of span on downstream side of box culverts on county road 468, 2.0 mi (3.2 km) upstream from Lake Okahumpka, and 5.0 mi (8.0 km) southeast of Wildwood.

CONTRIBUTING DRAINAGE AREA.--38 mi².

DATUM OF GAGE.-- 52.70 ft above NGVD 1929.

Date	Discharge (cubic foot per second)	Gage height (feet)	Date	Discharge (cubic foot per second)	Gage height (feet)
1979-09-27	180	7.46	1986-01-11	125	7.15
1980-04-05	70.0	M	1987-03-31	220	7.91
1980-11-18	22.0	5.61	1988-03-10	100	6.65
1982-06-18	128	7.17	1989-07-01	80.0	6.36
1983-04-24	161	7.36	1990-02-24	43.0	5.70
1984-05-28	97.0	6.79	1991-04-24	110	6.77
1985-09-03	40.0	5.59	1992-09-14	39.0	5.63

EXPLANATION OF PEAK DATA CODES

Discharge Qualification Codes	Gage Height Qualification Codes
¹ Discharge is a maximum daily average. ² Discharge is an estimate. ³ Discharge affected by dam failure. ⁴ Discharge less than indicated value, which is minimum recordable discharge at this site. ⁵ Discharge affected to unknown degree by regulation or diversion. ⁶ Discharge affected by regulation or diversion. ⁷ Discharge is an historic peak. ^B Month or day of occurrence is unknown or not exact. ^E Only annual maximum peak available for this year. ^M Missing value.	¹ Gage height affected by backwater. ² Gage height not the maximum for the year. ³ Gage height at different site and/or datum. ⁴ Gage height below minimum recordable elevation. ⁵ Gage height is an estimate. ⁶ Gage datum changed during this year. ^M Missing value.