




Figure 14. Bathymetric survey of the Missouri River channel in the vicinity of the main channel piers of structures K0456 and A0450 on U.S. Highway 69 in Kansas City, Missouri.