

## PAMLICO RIVER BASIN

354149075463901 CG #4 LAKE WORTH ROAD CANAL NEAR STUMPY POINT, NC - DOWNSTREAM STAGE

LOCATION.--Lat 35°41'49", long 75°46'39", Dare County, Hydrologic Unit 03020105, at downstream side of culvert on Lake Worth Road, 0.3 mi west of U.S. Highway 264, and 0.9 mi southwest of intersection of U.S. Highway 264 and Secondary Road 1100.

DRAINAGE AREA.--Indeterminate.

PERIOD OF RECORD.--October 1999 to September 2001 (discontinued).

GAGE.--Water-stage recorder. Datum of gage is sea level. Satellite telemetry at station.

REMARKS.--Station operated as part of a study conducted in cooperation with the U.S. Fish and Wildlife Service and the U.S. Air Force. Negative numbers represent water surface below sea level.

EXTREMES FOR PERIOD OF RECORD.--Maximum, 2.40 ft, Dec. 17, 2000; minimum, not determined.

GAGE HEIGHT, FEET, WATER YEAR OCTOBER 2000 TO SEPTEMBER 2001  
DAILY MEAN VALUES

DAY	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP
1	---	---	---	-.23	.09	.25	.51	.06	.73	.68	.55	.61
2	---	---	---	-.43	.14	.21	.71	.05	.89	.18	.56	.32
3	---	---	---	-.42	-.07	.19	.61	.05	.83	.26	.57	.53
4	---	---	---	-.27	-.11	.33	.19	.06	.50	.51	.55	.63
5	---	---	---	-.08	.12	.59	.40	.13	.61	.50	.46	.52
6	---	---	---	-.17	.19	.64	.65	-.62	.64	.15	.44	.46
7	---	---	---	-.09	.06	.50	.50	-.55	.62	.18	.55	.57
8	---	---	---	-.03	-.01	.67	.65	.14	.53	.50	.50	.57
9	---	---	---	.03	.01	.76	.73	.18	.51	.34	.50	.62
10	---	---	---	.20	-.05	.56	.49	.35	.57	.44	.51	.60
11	---	---	---	.10	-.76	.73	.63	.46	.58	.60	.51	.38
12	---	---	---	-.06	-.35	.56	.75	.59	.67	.29	.52	.52
13	---	---	---	-.14	-.29	1.00	.59	.10	.63	.35	.37	.65
14	---	---	.61	.20	-.07	.56	.46	.44	.70	.42	.25	.46
15	---	---	-.19	.23	-.02	.47	.81	.45	1.18	.47	.18	-.02
16	---	---	.36	.18	.08	.36	.47	.31	.81	.46	.50	.47
17	---	---	1.17	.14	-.27	.34	.53	.55	.59	.43	.52	1.13
18	---	---	.32	.10	-.16	.03	.80	.66	.42	.35	.61	1.10
19	---	---	.17	.31	.04	-.30	.43	.71	.53	.27	.71	.96
20	---	---	.22	.42	-.01	-.16	.29	.68	.51	.19	.81	1.04
21	---	---	.00	.43	-.13	.78	.25	.88	.50	.45	.61	1.07
22	---	---	-.10	-.11	-.33	.82	.09	1.06	.57	.76	.51	1.04
23	---	---	-.50	-.66	.16	.80	.04	.63	.80	.81	.62	.97
24	---	---	-.24	.25	-.08	.75	.12	.79	.50	1.03	.47	1.07
25	---	---	-.74	-.16	.27	-.04	-.73	.77	.50	.83	.13	1.00
26	---	---	-.44	.14	.01	.30	-.91	.76	.58	.71	.52	.85
27	---	---	-.30	.33	-.02	.25	.32	.97	.55	.29	.71	.72
28	---	---	-.65	.10	-.08	.21	.05	.87	.56	.39	.64	.50
29	---	---	-.55	.02	---	.41	-.10	.69	.50	.72	.52	.32
30	---	---	.06	.35	---	.62	.03	.67	.60	.35	.55	.28
31	---	---	.12	.31	---	.54	---	.47	---	.54	.68	---
MEAN	---	---	---	.03	-.06	.44	.35	.43	.62	.47	.52	.66
MAX	---	---	---	.43	.27	1.00	.81	1.06	1.18	1.03	.81	1.13
MIN	---	---	---	-.66	-.76	-.30	-.91	-.62	.42	.15	.13	-.02

354149075463901 CG #4 LAKE WORTH ROAD CANAL NEAR STUMPY POINT, NC - DOWNSTREAM STAGE--Continued

