


EXPLANATION

$\frac{D}{U}$ FAULT—Approximately located.
D, downthrown side; U, up-
thrown side

$\frac{200}{(60)}$ LINE OF EQUAL SATURATED
THICKNESS—Dashed where
approximately located. Interval
100 feet (30 metres)

Base from Wyoming Highway Department
county highway maps 1:126,720



Hydrology by G. C. Lines, 1975

FIGURE 6.—SATURATED THICKNESS OF THE ARIKAREE AQUIFER IN THE DWYER AREA, SOUTHEASTERN WYOMING, SEPTEMBER 1973