UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Prepared in Cooperation with
THE CLALLAM COUNTY BOARD OF COMMISSIONERS AND
THE STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

WATER RESOURCES INVESTIGATIONS 83-4227
PLATE 2

EXPLANATION

- Boundary of primary study area
- P1 ● Well and number (only wells which have been field checked are shown).
- H2 ↘ Observation well and number
- H1? 400 ↙ Dry hole, number, and depth drilled (in feet). A question mark after the number indicates the location was not field checked.
- 173 ▲ Surface-water gaging-station site and number.
- 204 △ Surface-water miscellaneous-measurement site and number.
- 181 ▼ Surface-water-quality site and number.
- ○ Ground-water site where water-quality limits (table 5) have been exceeded Fe, iron; Mn, manganese; pH; TB, turbidity.
- □ Surface-water site where water-quality limits (table 4) have been exceeed pH; CLR, color; TB, turbidity; COL, coliform.

Base from U.S.Geological Survey
Carlsborg, 1956, Dungeness, 1956,
Sequim, 1956, 40ft., Morse Creek,
1956, 50ft. Washington.

CONTOUR INTERVAL 40 AND 50 FEET
DASHED LINE REPRESENTS 20-FOOT CONTOURS
NATIONAL GEODETIC VERTICAL DATUM OF 1929

# SEQUIM-DUNGENESS PENINSULA