UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Prepared in Cooperation with
THE CLALLAM COUNTY BOARD OF COMMISSIONERS AND
THE STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

WATER RESOURCES INVESTIGATIONS 83-4227
PLATE 4

EXPLANATION

Symbol	Explanation
(solid line)	Boundary of primary study area
N2 ●	Well and number (only wells which have been field checked are shown).
M1 118 Ø	Dry hole, number, and depth drilled (in feet). A question mark after the number indicates the location was not field checked.
23 ▲	Surface-water gaging-station site and number.
34 (large ▲)	Surface-water crest-stage site and number.
16 △	Surface-water miscellaneous-measurement site and number.
82 ▼	Suface-water-quality site and number.
○	Ground-water site where water-quality limits (table 3) have been exceeded Fe, iron; Mn,manganese; pH; CLR, color; TB, turbidity.
□	Surface-water site where water-quality limits (table 4) have been exceeded Fe, iron; CLR, color; TB, turbidity; COL, coliform.



1 .5 0 1 2 3 4 MILES
1 0 1 2 3 4 5 KILOMETERS
CONTOUR INTERVAL 80 FEET
NATIONAL GEODETIC VERTICAL DATUM OF 1929

Base from U.S. Geological Survey
Pysht, 1957, Lake Pleasant, 1957,
80ft. La Push, 1956, Forks, 1957,
40ft. Washington.

SOLEDUCK-CALAWAH RIVER BASINS FROM LAPUSH TO SAPPHO AND ADJACENT AREAS