Prepared in cooperation with the

DEPARTMENT OF THE INTERIOR
UNITED STATES GEOLOGICAL SURVEY

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF ENVIRONMENTAL QUALITY ENGINEERING
DIVISION OF WATER POLLUTION CONTROL

WATER-RESOURCES INVESTIGATIONS
REPORT 84-4315 PLATE 1



Hydrologic-data collection sites and surface drainage divides of streams and representative storm sewers in the Lake Cochituate drainage basin, Massachusetts.