U.S. DEPARTMENT OF INTERIOR
U.S. GEOLOGICAL SURVEY

FIGURE 4.--MAP SHOWING SURFICIAL GEOLOGY, URBAN AREA, AND GAGING SITES, SODOM AND HARBOR BROOKS DRAINAGE BASINS, MERIDEN, CENTRAL CONNECTICUT

WATER RESOURCES INVESTIGATIONS
REPORT 89-4167



Base from U.S. Geological Survey
Meriden Quadrangle, 1:24,000, 1967, photorevised 1972,
Middletown Quadrangle, 1:24,000, 1965, photorevised 1984,
Wallingford Quadrangle, 1:24,000, 1967, photorevised 1984: and
Durham Quadrangle, 1:24,000, 1964, photorevised 1984

Geology from P.M. Hanshaw (1962)