

FLOOD OF JUNE 14-15, 1990, IN BELMONT, JEFFERSON,
AND HARRISON COUNTIES, OHIO, WITH EMPHASIS ON
PIPE AND WEGEE CREEK BASINS NEAR SHADYSIDE

By Harold L. Shindel

U.S. GEOLOGICAL SURVEY

Water-Resources Investigations Report 91-4147



Columbus, Ohio

1991

U.S. DEPARTMENT OF THE INTERIOR

MANUEL LUJAN, JR., Secretary

U.S. GEOLOGICAL SURVEY

Dallas L. Peck, Director

For additional information
write to:

District Chief
Water Resources Division
U.S. Geological Survey
975 W. Third Avenue
Columbus, OH 43212-3192

Copies of this report can
be purchased from:

U.S. Geological Survey
Books and Open-File Reports
Section
Box 25425
Denver Federal Center
Denver, CO 80225

CONTENTS

	Page
Glossary of terms-----	v
Abstract-----	1
Introduction-----	1
Purpose and scope-----	3
Acknowledgments-----	3
Weather associated with the flood-----	4
Antecedent conditions-----	4
Storms of June 14-15, 1990-----	7
Flooding in the Pipe and Wegee Creek basins near Shadyside, Ohio-----	7
Procedures used in data collection-----	7
Pipe Creek basin-----	9
Wegee Creek basin-----	11
Flooding in Belmont, Jefferson, and Harrison Counties-----	17
Areal distribution of flooding-----	22
Historical perspective-----	22
Summary and conclusions-----	24
Selected references-----	25
Supplemental information-----	27

ILLUSTRATIONS

Figures 1-5. Maps showing:	
1. Location of study area-----	2
2. May 1990 rainfall-----	5
3. Differences between normal May rainfall and May 1990 rainfall-----	6
4. Twenty-four-hour precipitation for the period ending 7:00 a.m., June 15, 1990--	8
5. Pipe Creek study area-----	10
6. Flood and streambed profiles of Pipe Creek for flood of June 14, 1990-----	12
7. Map showing Wegee Creek study area-----	16
8. Flood and streambed profiles of Wegee Creek for flood of June 14, 1990-----	18
9. Map showing continuous-record gaging sta- tions, partial-record crest-stage gages, and miscellaneous sites, with area recurrence intervals of the June 14, 1990, flood-----	21
10. Photoreproduction of front page of Bellaire Daily Leader for Monday, July 21, 1919-----	31

Table

Page

Table 1. Summary of hydrologic data for period of record and from the June 14-15, 1990, flood for selected sites in or near Belmont, Jefferson, and Harrison Counties----- 23

CONVERSION FACTORS AND VERTICAL DATUM

<u>Multiply</u>	<u>By</u>	<u>To obtain</u>
inch (in.)	25.4	millimeter
foot (ft)	0.3048	meter
mile (mi)	1.609	kilometer
square mile (mi ²)	2.590	square kilometer
cubic ₃ foot per second (ft ³ /s)	0.02832	cubic meter per second
cubic foot per second per ₃ square ₂ mile [(ft ³ /s)/mi ²]	0.01093	cubic meter per second per square kilometer

Sea level: In this report, "sea level" refers to the National Geodetic Vertical Datum of 1929--a geodetic datum derived from a general adjustment of the first-order level nets of the United States and Canada, formerly called Sea Level Datum of 1929.

GLOSSARY OF TERMS

The following are definitions of selected technical terms as they are used in this report; they are not necessarily the only valid definitions for these terms. Terms defined in the glossary are in **bold print** where first used in the main body of this report.

Continuous-record streamflow-gaging station.--A site at which gage height is measured repeatedly over time. Computation of a continuous-discharge record can be made from these measurements.

Discharge.--The volume of water that passes a given point within a given period of time. The unit of measurement used in this report is the cubic foot per second (ft^3/s), which represents a volume of 1 cubic foot passing a given point during 1 second (equivalent to 7.5 gallons per second).

Peak discharge.--The maximum discharge passing a point within a given time interval.

Unit discharge.--In reference to surface-water flow, the number of cubic feet per second from each square mile of area drained ($\text{ft}^3/\text{s}/\text{mi}^2$); uniform runoff in space is assumed.

Drainage area.--That area measured in a horizontal plane that contributes surface runoff to a specified location on a stream.

Evapotranspiration.--A collective term that includes water discharged to the atmosphere as a result of evaporation from the soil and surface-water bodies and by plant transpiration.

Lift.--A mechanism needed to bring warm air from the surface to the upper atmosphere. Such mechanisms include frontal systems, low-pressure troughs, effects of terrain, and convection (caused by land-air temperature differences).

Miscellaneous site.--A site at which data are collected on an intermittent basis.

Normal.--As used by meteorologists, the average (or mean) conditions over a specific 30-year period ending in a year evenly divisible by 10 (updated every 10 years). The period applicable for this report is 1951 through 1980.

Partial-record crest-stage gage.--A site where only the peak, or highest, gage height is determined for the interval between site visits. Measurement of peak gage height allows the computation of a peak discharge during that time period.

Percolation.--The slow movement of water through openings within a porous earth material.

Recurrence interval (RI).--The average interval of time within which the magnitude of a given event, such as a flood, will be equaled or exceeded. A recurrence interval of 100 years for a peak discharge indicates that a flow of that magnitude would be equaled or exceeded on the average of once every 100 years. It is possible, however, that a peak discharge of that magnitude can be equaled or exceeded more than once within a much shorter time period.

Stage.--The height of the water surface in a stream above a predetermined point, usually on or near the channel floor. Used interchangeably with gage height.

Water-surface elevation.--The stage referenced to sea level datum.

Streambed elevation.--Streambed referenced to sea level datum.

Streamflow-gaging station.--A site on a stream where systematic observation of gage height is obtained by some sort of recording equipment for the purpose of computing streamflow.

FLOOD OF JUNE 14-15, 1990, IN BELMONT, JEFFERSON, AND HARRISON
COUNTIES, OHIO, WITH EMPHASIS ON PIPE AND WEGEE CREEK BASINS NEAR
SHADYSIDE

By Harold L. Shindel

ABSTRACT


A series of violent thunderstorms caused severe floods and consequent damage in the central part of Ohio during June 14-15, 1990. The eastern part of the State, particularly Belmont, Harrison, and Jefferson Counties, sustained the most damage. In the Pipe and Wegee Creek basins near Shadyside, Belmont County, at least 24 people died and property damage exceeded \$10 million.

An indirect measurement of discharge on Pipe Creek, made near the mouth, indicates a peak discharge of 15,000 ft³/s (cubic feet per second) for the drainage area of 11.3 mi² (square miles) and a unit discharge of 1,330 (ft³/s)/mi² (cubic feet per second per square mile). The recurrence interval for this peak discharge is greater than 100 years. An indirect measurement of discharge on Wegee Creek, made 3 miles upstream from the mouth, indicates a peak discharge of 12,000 ft³/s for the drainage area of 5.46 mi² and a unit discharge of 2,200 (ft³/s)/mi². The recurrence interval for this peak discharge also is greater than 100 years. Longitudinal water-surface profiles showed depths ranging from 7 ft to 22 ft.

The severity of flooding was highly variable. For example, the recurrence interval of the peak discharge at one U.S. Geological Survey streamflow-gaging station was only 2 years, whereas the recurrence interval for the peak discharge was greater than 100 years at another gaging station about 22 miles away.

INTRODUCTION

At around 9:00 p.m., June 14, 1990, flood waves swept down Pipe and Wegee Creeks, two small creeks in eastern Ohio that are tributary to the Ohio River (fig. 1). According to witnesses, the flood waves, caused by an intense short-duration storm, were like walls of water as much as 20 ft high (Jacobs, 1990).



Base from U.S Geological Survey
 Clarksburg, West Virginia, Ohio,
 Pennsylvania 1:250,000. 1988

Figure 1.--Location of study area.

At least 24 people lost their lives in these two basins. Twelve people were killed on Wegee Creek; twelve were killed on Pipe Creek. Two other deaths resulted from flooding on another nearby creek. A number of factors led to the high fatality rate, but the most significant were the time that the flooding took place (9:00-9:30 p.m.) and the suddenness of the flooding.

Damages were reported in at least 18 counties in central Ohio. The damage estimates listed below for Belmont, Harrison, and Jefferson Counties (G. Keller, State of Ohio Adjutant General's department, written commun., 1990) are based solely on the approved county Damage Survey Reports.

Belmont-----	\$2,107,615
Harrison-----	1,287,446
Jefferson-----	1,636,830

The U.S. Army Corps of Engineers, Pittsburgh District, reported a higher damage total, \$10.1 million, for the Pipe and Wegee Creek basins, with the damage divided about evenly between the two basins (Michael Irr, U.S. Army Corps of Engineers, oral commun., 1991). The damage estimate included 145 residences damaged and 58 destroyed, infrastructure repairs, relief efforts, and reconstruction expenses. The Corps of Engineers assessment included many items not accounted for in the county Damage Survey Reports.

Purpose and Scope

This report describes the weather and flooding of June 14-15, 1990, in Belmont, Harrison, and Jefferson Counties, with emphasis on the Pipe and Wegee Creek basins. Specific hydrologic data are presented for the three-county area on the basis of existing U.S. Geological Survey (USGS) **streamflow-gaging stations**¹ in the area. **Peak water-surface elevations** were determined at points along Pipe and Wegee Creeks to develop flood profiles. Indirect determinations of **discharge** were made at one location on each of these ungaged streams. The history of flooding in the area is discussed.

Acknowledgments

Much of the data collection and interpretation were based on the combined efforts of many individuals in the private and public sectors. Much of the information in the Supplemental Information section was provided by Margaret Kirkland, a local resident and retired educator currently working on a history of Belmont County.

¹ Terms defined in the glossary are in bold print where first used in the main body of this report.

Weather-condition reports were provided by the Ohio Department of Natural Resources (ODNR) and the National Weather Service (NWS). Damage assessment in the three-county area was furnished by the State Disaster Relief Agency, and the assessment of damages in the Pipe and Wegee basins was provided by the U.S. Army Corps of Engineers, Pittsburgh District.

WEATHER ASSOCIATED WITH THE FLOOD

The storms of June 14-15, 1990, followed an unusually wet spring in eastern Ohio. The severity of the flooding was partly due to the inability of the saturated soils to absorb storm rainfall.

Antecedent Conditions

Rainfall was above normal throughout the State for the months of January through April 1990. The average precipitation for the State for that period was 18.68 in., 3.04 in. above normal. Regional averages ranged from 5.81 in. above normal for the Southwest region to 1.65 in. above normal for the North Central region (Cashell, 1990).


Average rainfall for May 1990 was above normal. The average rainfall for the State in May 1990 was 7.06 in., 3.31 in. above normal. May 1990 was ranked as the second wettest May on record in 108 years. Regional averages ranged from 5.92 in. above normal for the Southwest region to 1.37 in. above normal for the North Central region. During May 3-4, more than 2 in. of rain fell at many locations from the southwestern to north-central parts of the State. From 2 to 3 in. of rain fell in the southern two-thirds of Ohio during May 13-17. Many locations in southeastern Ohio received another 2 in. of rain during May 25-26. On May 28, the southern half of the State received an additional 2 to 4 in. of rain.

Rainfall during May 1990 is shown in figure 2. The average precipitation in each of the regions and the May 1990 departure expressed as a percentage of normal are shown in figure 3.

The amount of water in the soils of eastern Ohio during this period is indicated by the Palmer Drought Severity Index (National Weather Service, 1990), which depicts prolonged abnormal dryness or wetness. This index usually responds slowly (changes little from week to week) and reflects long-term changes in moisture, runoff, recharge, deep percolation, and evapotranspiration rates. The Palmer Index at the end of May for the Southeast region of the State (where Pipe and Wegee Creeks are located) was +2.7 (Cashell, 1990), which indicates an




Data from Ohio Department of Natural Resources, 1990




EXPLANATION

— 6 — LINE OF EQUAL PRECIPITATION—Contour interval 1 inch

Figure 2.--May 1990 rainfall.



Data from Ohio Department of Natural Resources, 1990



EXPLANATION

7.45 AVERAGE--in inches
196 PERCENT OF NORMAL

Figure 3.--Differences between normal May rainfall and May 1990 rainfall.

"Unusual Moist Spell." By June 9, 1990, the Palmer Index for the Southeast region was about 3.2 (National Weather Service, 1990), which indicates a "Very Moist Spell." This relatively rapid change indicates the unusual spring wetness.

Storms of June 14-15, 1990

On June 14, 1990, a series of slow-moving thunderstorms moved eastward across the midsection of Ohio. Isolated storm cells delivered from 1 in. to more than 3 in. of rain at many locations. A total of 5 in. of rain fell on the Belmont-Harrison-Jefferson County area over a 24-hour period.

In an extensive analysis of this storm (National Weather Service, 1991), the NWS found that three key conditions conducive to thunderstorms existed: moisture, instability, and a source of lift. A weak upper-air disturbance crossed Ohio from west to east during the day. By evening, a low-pressure system had developed over southeastern Ohio, which had the effect of drawing moisture-laden air into the atmosphere over the three-county area. Instability of the various air masses increased during the day, especially over east-central and southern Ohio. The amount of moisture in the air increased as the upper-air temperatures rose. At 8:00 p.m., the amount of water in the air was 160 to 190 percent of normal.

One of the end results of all this activity was the generation of a high-intensity thunderstorm over the three-county area. According to the National Weather Service (1991), this storm delivered 3 to 4 in. of rain between 8:30 and 9:45 p.m. The greatest rainfall occurred in a band from southeastern Harrison County to northeastern Belmont County.



The 24-hour precipitation across the southern two-thirds of Ohio is shown in figure 4. The area of greatest rainfall was centered on Belmont, Harrison, and Jefferson Counties.

FLOODING IN THE PIPE AND WEGEE CREEK BASINS NEAR SHADYSIDE, OHIO

Flood marks and the high-water profiles are presented in the Pipe Creek basin and Wegee Creek basin sections of the report.

Procedures Used in Data Collection

High-water marks along both banks of Pipe and Wegee Creeks were flagged on June 16, 17, 21, and 22, 1990. These marks and streambed elevations were subsequently referenced to sea level by field surveys.



EXPLANATION

— 2 — LINES OF EQUAL PRECIPITATION, IN INCHES

Figure 4.--Twenty-four-hour precipitation for the period ending 7:00 a.m., June 15, 1990.

All surveyed points are plotted in figures 6 and 8. Some parts of the profiles were obtained by averaging several points. Because of a number of factors, including high velocities, steep channel slopes, turbulent flow, and debris, judgment was used in determining the water-surface profile. The lines connecting the points do not necessarily represent the actual water-surface or streambed profile but are presented as a visual aid.

Indirect measurements were necessary to estimate the peak discharges because the suddenness and short duration of the flood made direct measurement impossible. In indirect measurements, information recovered after a flood is used to estimate the peak discharge of the flood. After preliminary reconnaissance of the Pipe Creek and Wegee Creek basins, a suitable reach was found on each stream to make an indirect measurement of the peak discharge by the slope-area method.

The slope-area method is one of the most commonly used methods for indirect determinations of discharge. In the slope-area method, discharge is computed on the basis of the Manning equation. This gradually varied flow equation is always used:

$$Q = (1.486/n)AR^{2/3}S^{1/2},$$

where


- Q is the discharge, in cubic feet per second;
- A is the cross-sectional area of the channel, in square feet;
- R is the hydraulic radius, in feet;
- S is the friction slope, in feet/foot; and
- n is the Manning roughness coefficient.

Field surveys are necessary to define the water-surface profile through the reach and to determine the cross-section characteristics. Among these characteristics is the roughness coefficient, which is based on the physical characteristics of the stream and the flood plain.

Peak discharges for Pipe and Wegee Creeks were determined by use of the USGS computer algorithm for slope-area measurements (O.G. Lara and Jacob Davidian, U.S. Geological Survey, written commun., 1970).

Pipe Creek Basin

The headwaters of Pipe Creek are 1.5 mi west of Key, Ohio, although the headwaters of one of the tributaries to Pipe Creek are just south of Key (figs. 1 and 5). Pipe Creek flows through an area of steep slopes. For most of the length of the basin, the slopes of adjacent hills are approximately 30 degrees.



Base from U.S. Geological Survey
 Armstrongs Mill, Ohio 1960,
 photorevised 1972.
 Businessburg, Ohio 1960,
 photorevised 1972 and 1976

EXPLANATION

- [] PROFILE SECTION
- ▲ INDIRECT-MEASUREMENT SITE
- 10 DISTANCE FROM MOUTH— in thousands of feet




Figure 5.--Pipe Creek study area.

The basin elevation ranges from 1,350 ft above sea level at the headwaters to 625 ft above sea level at the mouth. The drainage area of Pipe Creek is 12.5 mi² at the mouth.

The flood profile reach extends from the mouth to a point about 6.8 mi upstream. The width of the valley floor averages 200 to 250 ft for most of the reach but exceeds 500 ft in places. The difference in streambed elevation from near the mouth (618 ft) to the head of the study reach (1,063 ft) is 445 ft. The average channel slope is 0.0124 ft/ft or 65.3 ft/mi.

The peak discharge on Pipe Creek at the indirect measurement site, 4,600 ft upstream from the mouth (drainage area, 11.3 mi²), was 15,000 ft³/s. This discharge corresponds to a unit discharge of 1,330 (ft³/s)/mi². A recurrence interval could not be computed because historical data are not available. A regional regression equation for flood-frequency (Koltun and Roberts, 1990) was used to estimate discharge for a 100-year flood at this site. On the basis of the regional equation estimate of 3,440 ft³/s, the peak discharge of 15,000 ft³/s is well in excess of a 100-year flood. The water-surface elevation at the downstream end of the indirect-measurement reach (4,600 ft upstream from the mouth) was 665 ft above sea level, which corresponds to a stream depth of 12 ft.

The flood profile shown in figure 6 essentially paralleled the streambed profile, although, in some cases, the floodwater surface was unaffected by small waterfalls and irregularities in the channel. The lack of effect of channel features can be seen in the profile at the waterfalls 12,000 and 17,000 ft upstream from the mouth and at a series of smaller waterfalls that are between 25,000 to 33,500 ft upstream from the mouth. Large waterfalls, such as the one 6,500 ft upstream from the mouth, affect the water surface. Stream depths in the reach averaged 14 ft and ranged from 7 ft near the headwaters to 17 ft near the mouth.

Wegee Creek Basin

The headwaters of Wegee Creek rise near the village of Key, Ohio, which is 6 mi west of Shadyside, Ohio (figs. 1 and 7). The stream is in an area of steep slopes. For most of the length of the basin, the slopes of adjacent hills are approximately 30 degrees. The land-surface elevation ranges from about 1,300 ft above sea level at the headwaters to about 630 ft at its mouth on the Ohio River (at River Mile 98.7). The drainage area of Wegee Creek is 12.8 mi² at the mouth.




Figure 6.--Flood and streambed profiles of Pipe Creek for flood of June 14, 1990--Continued.




Figure 6.--Flood and streambed profiles of Pipe Creek for flood of June 14, 1990--Continued.




Figure 6.--Flood and streambed profiles of Pipe Creek for flood of June 14, 1990--Continued.




Figure 6.--Flood and streambed profiles of Pipe Creek for flood of June 14, 1990.




Figure 7.--Wegee Creek study area.

The flood-profile reach extends from the mouth to a point about 5.4 mi upstream. The width of the valley floor averages 200 to 250 ft for most of the length of the reach, but widths are as great as 700 ft in places. The valley widens considerably near the mouth. The difference in streambed elevation from the mouth (610 ft) to the head of the study reach (940 ft) is 330 ft. The average channel slope in the study reach is 0.0116 ft/ft, or 61.1 ft/mi.

The peak discharge on Wegee Creek at the indirect measurement site, 17,000 ft upstream from the mouth (drainage area, 5.46 mi²), was approximately 12,000 ft³/s. This discharge corresponds to a unit discharge of 2,200 (ft³/s)/mi². A recurrence interval could not be computed because historical data are not available. On the basis of the regional equation estimate of 1,950 ft³/s, the peak discharge of 12,000 ft³/s was well in excess of a 100-year flood. The water-surface elevation at the downstream end of the indirect-measurement reach (16,500 ft upstream from the mouth) was 812 ft above sea level, corresponding to a stream depth of 16 ft.

The flood profile shown in figure 8 generally paralleled the streambed profile, although, in some cases, the water surface was unaffected by some of the irregularities in the stream channel. For example, the series of 3- to 5-foot-high waterfalls in the reach 16,000 to 18,500 ft upstream from the mouth does not affect the flood profile. At the 14-foot-high waterfall and pool 10,000 ft upstream from the mouth, however, the profile is affected. Stream depths in the reach averaged 16 ft and ranged from 10 ft in steep sections to 22 ft at the mouth.

FLOODING IN BELMONT, JEFFERSON, AND HARRISON COUNTIES

Two types of streamflow gages were used to analyze the areal distribution of the flood of June 14-15, 1990 (fig. 9). The progression of the flood, its peak, and its recession were recorded at three continuous-record streamflow-gaging stations: Short Creek near Dillonvale (03111500), Wheeling Creek below Blaine (0311548), and Captina Creek at Armstrongs Mills (03114000). Peak discharges north and west of the continuous-record stations were determined from three partial-record crest-stage gages: Clear Fork near Jewett (03127950), Branson Run at Georgetown (0311450), and South Fork Short Creek at Georgetown (03111455). These partial-record crest-stage gages had been discontinued in 1987, but high-water marks at these gages were obtained and used in this study.

No streamflow gages were ever established on Pipe and Wegee Creeks. Discharge for the miscellaneous sites on Pipe and Wegee Creeks were determined from indirect measurements made after the




Figure 8.--Flood and streambed profiles of Wegee Creek for flood of June 14, 1990--Continued.




Figure 8.--Flood and streambed profiles of Wegee Creek for flood of June 14, 1990--Continued.





Figure 8.--Flood and streambed profiles of Wegee Creek for flood of June 14, 1990.



EXPLANATION



- ▲ STREAMFLOW-MEASUREMENT STATIONS AND SITES--Eight- or fifteen-digit number adjacent to symbol is the station or site number
- ▲ Continuous-record station
- ▲ Crest-stage station
- △ Indirect-measurement site
- RI=2 RECURRENCE INTERVAL, IN YEARS-->, greater than; see Table 1

Figure 9.--Continuous-record gaging stations, partial-record crest-stage gages, and miscellaneous sites with area recurrence intervals of the June 14, 1990, flood.

flood on June 14-15. Information from the continuous-record stations, partial-record crest-stage gages, and indirect measurements are summarized in figure 9 and in table 1.

Areal Distribution of Flooding

Flood severity varied considerably throughout the three-county area. Recurrence intervals of peak discharges at the stations listed in table 1 range from 2 years to greater than 100 years. The maximum discharge for the period of record was recorded during this flood at the Short Creek streamflow-gaging station. Short Creek and Captina Creek are 22 mi apart; however, the recurrence interval of the peak discharge at the Captina Creek station was 2 years, whereas the recurrence interval of the peak discharge at the Short Creek station was greater than 100 years. Similarly, the peak discharge at the miscellaneous site on Pipe Creek was 15,000 ft³/s with a recurrence interval greater than 100 years, whereas the Captina Creek peak discharge was 6,080 ft³/s with a recurrence interval of 2 years; these two sites are only 5 mi apart.

Historical Perspective

Flash flooding on streams in Belmont, Jefferson, and Harrison Counties is not uncommon. Numerous floods are noted throughout the historical records of this area; accounts of many of these floods have been compiled in the "Supplemental Information" section at the back of this report. Some of those past floods could have been as hydrologically significant as the flood of June 14-15, 1990, but may have caused much less damage. According to Margaret Kirkland, a resident of Belmont County and a local historian, "Since World War II, more people live in these creek valleys, especially with the popularity of mobile homes as a way of living. Much of the land in the creek valleys used to be farmed but is now used for home sites."

Historical accounts indicate that as many as six major floods may have occurred in the three-county area since the early 1800's. Most of the small streams in the area have never been part of a systematic streamflow-data-collection network, however, so there is no scientific basis for corroborating historical accounts of flooding. Paleoflood investigations--studies of prehistoric movement of water and sediment in channels--have been shown to produce reasonable estimates of flood magnitude and frequency in areas where systematic streamflow data are lacking (Hupp, 1987). Paleoflood investigations may ultimately be necessary if a scientific approach is taken for determining regional probabilities of major flooding in narrow stream valleys of Belmont, Jefferson, and Harrison Counties.

Table 1.--Hydrologic data for period of record and from the June 14-15, 1990, flood for selected sites in or near Belmont, Jefferson, and Harrison Counties, Ohio

[bl, below; C, Creek; F, Fork; nr, near; and rn, Run; >, greater than; ft³/s, cubic foot per second; [(ft³/s)/mi²], cubic foot per second per square mile; and mi², square mile]

Station number	Station name	Drainage area (mi ²)	Period of record	Maximum prior to June 1990		Date	Maximum for June 14-15, 1990		Unit discharge [(ft ³ /s)/mi ²]	Recurrence interval (years)
				Dis-charge (ft ³ /s)	Dis-charge (ft ³ /s)		Dis-charge (ft ³ /s)	Dis-charge (ft ³ /s)		
<u>Continuous-record stations</u>										
03111500	Short C nr Dillonvale	123	10/41 to date	6,500	6,500	03/06/45	8,200	66.7	>100	
03111548	Wheeling C bl Blaine	97.7	12/82 to 09/87 10/88 to date	3,780	3,780	06/21/89	4,840	49.5	5-10	
03114000	Captina C at Armstrongs Mills	134	08/26 to 09/35 10/58 to date	21,900	21,900	08/11/80	6,080	45.4	2	
<u>Partial-record crest-stage gages</u>										
03111450	Branson Rn at Georgetown	1.31	08/77 to 09/87	134	134	06/07/78	190	145	25	
03111455	South F Short C at Georgetown	10.9	08/77 to 09/87	380	380	08/18/80	620	56.9	25-50	
03127950	Clear F nr Jewett	5.45	08/77 to 09/87	300	300	07/14/78	1,270	233	50-100	
<u>Indirect-measurement sites</u>										
395709080491600	Pipe C at Vadis	11.3	[None]	[No data]	[No data]		15,000	1,330	>100	
395734080480400	Wegee C nr Webb	5.46	[None]	[No data]	[No data]		12,000	2,200	>100	

SUMMARY AND CONCLUSIONS

Storms during the evening of June 14, 1990, caused extensive flooding in Ohio, with disastrous results in the Pipe and Wegee Creek basins. An extremely wet spring reduced the soil's capacity to absorb any significant additional precipitation. The strong line of thunderstorms that moved across the State on June 14 culminated in an unusually severe weather pattern, which produced roughly 3 to 5 inches of rain over the three-county area during the early evening hours when most people were at home. The steep narrow valleys of the Pipe and Wegee Creek basins concentrated the flow and produced flash flooding. At least 24 people lost their lives, and millions of dollars in damage was done.

An indirect measurement made 4,600 ft upstream from the mouth of Pipe Creek indicated a peak discharge of $15,000 \text{ ft}^3/\text{s}$ and a corresponding unit discharge of $1,330 \text{ (ft/s)/mi}^2$. An indirect measurement made 17,000 ft upstream from the mouth of Wegee Creek indicated a peak discharge of $12,000 \text{ ft}^3/\text{s}$ and a corresponding unit discharge of $2,200 \text{ ft}^3/\text{s}$. The recurrence interval for each of these peak discharges is greater than 100 years.

The average depth of water in Pipe Creek was 14 ft for the entire surveyed reach and ranged from 7 ft near the headwaters to 17 ft near the mouth. The average depth of water in Wegee Creek for the entire surveyed reach was 16 ft and ranged from 10 ft in steep sections to 22 ft at the mouth.

Flood severity varied considerably throughout the three-county area. Recurrence intervals of peak discharges at the stations listed in table 1 range from 2 years to greater than 100 years. The maximum discharge for the period of record was recorded during this flood at the Short Creek streamflow-gaging station. Short Creek and Captina Creek are 22 mi apart; however, the recurrence interval of the peak discharge at the Captina Creek station was 2 years, whereas the recurrence interval of the peak discharge at the Short Creek station was greater than 100 years. Similarly, the peak discharge at the miscellaneous site on Pipe Creek was $15,000 \text{ ft}^3/\text{s}$ with a recurrence interval greater than 100 years, whereas the Captina Creek peak discharge was $6,080 \text{ ft}^3/\text{s}$ with a recurrence interval of 2 years; these two sites are only 5 mi apart.

Results of statistical analyses contrast with reports of severity and frequency of flooding in historical accounts from the three-county area. For example, the peak discharge on Wegee Creek was more than six times that of the 100-year flood estimated by use of the regional equation; yet, historical accounts indicate that floods of similar magnitude may have occurred at least two other times in the last 100 years. Paleoflood investigations may be necessary to resolve the apparent discrepancies.

SELECTED REFERENCES

- Beaulieu, L.S., 1990, Town center little touched by waters:
Columbus (Ohio) Dispatch, June 17, 1990, p. 1D.
- 1990, Raging water brings death, destruction:
Columbus (Ohio) Dispatch, June 16, 1990, p. 1A.
- Bellaire Daily Leader, 1919, Nine lives and property loss estimated at million is toll of flood in the valley of Wegee Creek: July 21, 1919, p. 1.
- Caldwell, J.A., 1880, History of Belmont and Jefferson Counties: Wheeling, W. Va., Historical Publication company (Reprinted in Evansville, Ind., by Unigraphic, 1976), 611 p.
- Cashell, D.H., 1990, Monthly water inventory report for Ohio: Ohio Department of Natural Resources, May, 4 p.
- Dalrymple, Tate, and Benson, M.A., 1967, Measurement of peak discharge by the slope-area method: U.S. Geological Survey Techniques of Water-Resources Investigations, book 3, chap. A2, 12 p.
- Hupp, C.R., 1987, Botanical evidence of floods and paleohistory, in Singh, V.P., ed., Regional flood frequency analysis: Dordrecht, Holland, D. Reidel Publishing Company, p. 355-369.
- Jacobs, David, 1990, 9-year-old girl survives watery nightmare: Columbus (Ohio) Dispatch, June 16, 1990, p. 1A.
- Jarrett, R.D., and Costa, J.E., 1986, Hydrology, geomorphology, and dam break modeling of the July 15, 1982 Lawn Lake Dam and Cascade Lake Dam failures, Larimer County, Colorado: U.S. Geological Survey Professional Paper 1369, 78 p.
- Koltun, G.F., and Roberts, J.W., 1990, Techniques for estimating flood-peak discharges of rural, unregulated streams in Ohio: U.S. Geological Survey Water-Resources Investigations Report 89-4126, 68 p.
- McKelvey, A.T., 1903, Centennial history of Belmont County: Chicago, Ill., Biographical Publishing Co. (Reprinted in Knightown, Ind., by Bookmark, 1977), 833 p.
- National Weather Service, 1990, Drought severity index by division: Weekly Weather and Crop Bulletin, June 9, 1990: p. 5.
- 1991, Natural disaster survey report, Shadyside, Ohio-- flash floods, June 14, 1990: 48 p.


Shindel, H.L., and others, 1990, Water resources data, Ohio, water year 1989: U.S. Geological Survey Water-Data Report OH-89-1, 312 p.

Switzer, John, 1990, County declared disaster area: Columbus (Ohio) Dispatch, June 16, 1990, p. 12A.

Trieste, D.J., and Jarrett, R.D., 1987, Roughness coefficients of large floods, in James, L.G., and English, M.J., eds., Irrigation and Drainage Division Specialty Conference--Irrigation systems for the 21st century, Portland, Or., 1987, Proceedings: New York, American Society of Civil Engineers, p. 32-40.

SUPPLEMENTAL INFORMATION

BACKWARD GLANCES



WEGEE CREEK, near Shadyside, flooded in July 19, 1919, sweeping across the adjacent cemetery and carrying bones down stream. The rails in that area were thrown onto the

cemetery ground and a number of people drowned near what is now the Shadyside Lions Club.

Photograph of photocopy from Martins Ferry Times-Leader Newspaper, courtesy of Margaret Kirkland.

SUPPLEMENTAL INFORMATION

Much of this section was developed from information supplied by Margaret Kirkland (written commun., 1990), a retired educator currently working on a publication of Belmont County's history. Her work is based on newspaper files, Caldwell's "History of Belmont and Jefferson Counties" (1880), McKelvey's "Centennial History of Belmont County" (1903), and interviews of a number of county residents.

The following quotations are excerpts from various historical and eyewitness accounts of past flooding in the three-county area.

Flood of 1818--Hardesty Flood

The flood known as the Hardesty Flood occurred in about 1818 on McMahon's Creek. It was styled thus owing to the fact that Mr. John Hardesty and family--wife and five children--were drowned in it. He lived near the banks of this stream and the waters rose to such a height that his house was inundated and carried off on the resistless bosom of the angry turbid waters. After the waters had abated he and his wife's body were recovered a short distance from where the house stood. The remains of two of his children were regained a considerable distance below, in the stream. The other children were never found. Major Thompson, of St. Clairsville, says, that several days after the flood, he passed down that way on horseback, and saw straw and litter lodged on the branches of trees along the creek, so high above him that he was unable to reach with his whip from his horse. The ravages of the flood were immense with great loss of property. It is said that the waters came down with such power as to cause the drift, bourne on its bosom, to be swept across on the opposite banks of the Ohio River.

(Caldwell, 1880)

Flash Flood of 1866

On Sabbath evening, August 12, 1866, the storm swept over Wheeling Creek Valley from Flushing on the west to the Ohio River and beyond. For hours the sky was illuminated by continuous streams of lightning. The thunder pealed continuously and the rain fell in torrents. In a few hours Wheeling Creek had overflowed its banks and, at a point between Barton and the foot of the "big hill" the log house of Kellis Robinson was washed away, and father, mother, and five children were drowned. At Oglebay's Mill, the creek broke over the narrow channel that carried water into the dam, and washed nearly an acre of land away, the course of the stream was completely changed.

* * *

The loss of personal property was terrible--some farmers lost their entire crop, fields of corn ranging from 10 to 30 acres were completely washed away and several small bridges between the foot of the "big hill" and Bridgeport were destroyed. In addition to the seven drowned, two were killed by lightning.

(McKelvey, 1903)

Flood of 1881

In the month of May, 1881, a rain storm of a character similar to that narrated above broke over St. Clairsville and the county northward. The little stream running north of the town and known as "Jug Run" became a raging canal of water that swept its narrow channel from bank to bank, carrying off everything that was moveable. Along the line of "Jug Run" fences and bridges were washed away, and the road was literally destroyed.

The St. Clairsville & Northern Railroad had just been completed at an expense of about \$30,000 and in a brief hour was undone, and it became necessary to build the road anew. Many families were driven out of their homes by the water and numbers barely escaped with their lives.

(McKelvey, 1903)

Flood of 1884

[The Great Flood of 1884] nearly destroyed Businessburg. The waters of Pipe Creek rose to a height of 15 feet, and the town was practically submerged. Many houses were carried away and the loss was very heavy.

(McKelvey, 1903)

Flood of 1888

The year following the great cyclone of 1887, previously mentioned, the St. Clairsville branch of the Baltimore and Ohio Railroad, with the exception of a mile or more near St. Clairsville, was literally washed away by an unprecedented flood on Little McMechen's (McMahon's) Creek. The rain storm was a veritable cloudburst, washing away houses, bridges, and fences. A great wall of water surrounded an approaching train with a passenger coach well filled with passengers. The train was compelled to stop and although the water nearly engulfed it, the engine and car withstood the shock and the passengers were saved. Nearly everyone living on the borders of the creek suffered and the railroad was so badly damaged it was necessary to rebuild it. The loss was estimated at \$200,000.

(McKelvey, 1903)

Flood of 1896

"WEGEE CREEK VALLEY SWEEPED BEFORE"

It was almost 23 years to a day from the awful catastrophe of Saturday night, that Wegee Creek first overflowed its banks to a depth of 30 feet and swept everything before it. That the property damage and loss of life in the first flood was not greater than that Saturday night was due only to the fact that the creek valley was not nearly so thickly populated as it is at the present time.

Three were drowned in the flood of 23 years ago, consisting of a man, his wife, and one child. They resided in the valley of the creek and the water came up so rapidly that they were caught unaware. Their bodies were never recovered.

Crops in the creek valley at that time were ruined and the damage totalled thousands of dollars.

(Bellaire Daily Leader, July, 1919, [Fig. 10])

THE NEWSPAPER THAT GOES HOME

Bellaire Daily Leader

THE HOME PAPER FOR HOME PEOPLE

VOLUME VII, NO. 04

BELLAIRE, OHIO, MONDAY EVENING, JULY 21, 1919.

PRICE TWO CENTS

Nine Lives And Property Loss Estimated At Million Is Toll Of Flood In The Valley Of Weegee Creek

PARTIES CONTINUE SEARCH FOR BOIES OF THOSE WHO DROWNED IN DELUGE OF SATURDAY NIGHT

Nine lives and property loss totalling a million dollars is the toll of the storm which swept Eastern Ohio Saturday afternoon and evening. On Weegee creek at Mapleton, just one half a mile above the Webb mine two lives were swept away and the occupants which are as follows were drowned: Mrs. John Hatfield, age 42 years. John Hatfield, Jr., age 10 years. Mike Hatfield, age 7 years. Mary Hatfield, age 6 years. Mrs. Pearl Steve, age 45 years. Stella Steve, age 5 years. Mary and Margaret Steve, twins, age three years. Helen Steve, age one month. The bodies of two of the Hatfield family, Mary and Mike and two of the Steve family Mary and Stella were recovered yesterday. It is the consensus of opinion that the others were swept into the Ohio river by the raging torrent.

TRIED TO SAVE FAMILY According to the story related to a Leader Reporter by Marie Steve, a member of the deceased family, the storm at Mapleton was practically a cloud burst. John Steve and the three oldest boys were absent from the home when the storm set in. As the creek began to rise Moxie Steve, worried by a mother that it was time to leave the home, fled into the woods and continued to watch the rapidly rising creek. When his waters surrounded the home he pleaded with his mother to leave but she was determined to stand by her home. Most went to a front window and saw the home of the Hatfield family spinning down the stream. As the waters began to rise and two one end from the building. As the waters began to pour into his home Moxie grasped the twins, Mary and Walter, under his arm and attempted to wade to the hillside. They were caught in the current and the children were whisked out from his grasp. Moxie was whirled down stream of a rock but he managed to catch onto a pile of drift wood and was whirled into an eddy where he was later rescued by a party of miners.

TORRENT OF WATER He stated yesterday that the run, a tributary to Weegee creek began to rise shortly after the rain struck Weegee. It was a raging torrent inside of fifteen minutes and suddenly a wall of water at least fifteen feet high swept down the valley, carrying everything before it. The Hatfield family was at home at the time of the deluge and refused to heed the warnings of the miners who came down the valley. When the home was swept from its foundation, the father who was standing on the porch was swept into the flood. He managed to grasp a log and was thrown into a tree. It being there for several hours and when the waters finally receded he was rescued.

Both the Hatfield and the Steve houses were whirled against the O. R. & W. railroad bridge and reduced to splinters. When the bridges finally gave way, the debris was whirled down stream and into the Ohio river. The five missing persons are believed to have been swept into the river, but some of the bodies are found in the numerous piles of driftwood that mark the course of the flood. Since the waters began to recede, searching parties have been at work in an effort to locate the bodies of the unfortunate victims of the deluge. Three bodies were recovered yesterday morning, all children. The search was continued all day Sunday and this morning but no more bodies were found. The remains of the four children were removed to the Grafen morgue, yesterday afternoon but no arrangements have been made for the funerals. Doctor John H. West has been conducting an investigation and assists in the search for the missing bodies.

NARROW ESCAPE In addition to the two houses at Mapleton, another home at Webb was carried away by the flood. The home of John Platt situated just below the company's bridge was carried away and Mrs. Platt and two children had a narrow escape from drowning. When the waters surrounded the home, Mrs. Platt and her two children jumped from the front porch. They were caught in the swirling stream and carried a short distance down the creek where they were rescued by a party of miners. The home of Adolph Mierow which is located just a short distance above the Platt home miraculously escaped destruction. It is situated just a short distance above the Platt home and the bridge was a pile of driftwood which collapsed against the west end of the building. It is without doubt the only building in the vicinity which escaped destruction.

WEATHER The weather was clear and warm at the time of the deluge. The wind was from the west and the temperature was in the upper 70s. The rain fell in a steady shower for several hours, beginning about 8 o'clock and continuing until about 11 o'clock. The total rainfall was about 1.5 inches.

CAR STRIKE AT CHICAGO IS AVERTED

Chicago, July 21.—The threatened strike of 16,000 of Elevated and Street Railway employees will be averted, it is declared today through the granting of reasonable wage increases to the men, but car fare will go up. Indications were that the State Public Utilities will grant the traction companies permission to increase fares sufficiently to cover the expense the increased wages paid to employees would entail. The employees, it is declared, are prepared to accept a compromise scale somewhat less than that of the increase originally demanded. The strike of 10,000 street car employees ended today and they are preparing to return to work. They are preparing to return to work. They are preparing to return to work.

Newark Carrier Leading In The Sale Of Stamps

Columbus, Ohio, July 21.—(Special.)—A record that is attracting attention from all over the United States is held by James C. Cooper a letter carrier of Newark. According to the Ohio War Savings Stamp office he has sold War Savings Stamps amounting to more than \$50,000 during the last several months. Some idea of the magnitude of the remarkable endeavor is gained when it is realized that War Savings Stamps sell for less than 85¢ each which means that Cooper has sold more than 10,000 stamps. A. H. Store of Columbus alone secured with a sale of \$40,350, while E. A. Keller of Columbus, is third with \$44,000. These letters carry the emblem of the United States War Savings Stamp advertisement and the letter carriers of the United States, having sold more War Savings Stamps than any other mail carriers in this country.

Glittering War Stamp sales were among the letter carriers of Ohio and the amount of their sales are: A. L. Nussbaum, Ashland, \$22,000; William Lutz, Zanesville, \$24,000; D. E. Brumfield, Wellston, \$31,000; J. F. Butler, Brown, \$30,000; C. J. Donnelly, Marine, \$30,000; J. C. Bell, Hamilton, \$25,100; J. H. Siers, Mansfield, \$25,200; J. L. Kitchell, Jewett, \$24,000; J. H. Schaefer, Chillicothe, \$22,800; Walter Bragg, Mt. Gilead, \$23,700; W. L. Schneider, Chillicothe, \$22,800; C. J. McKee, Coalington, \$21,100; William E. Stewart, Bellefontaine, \$20,910; H. C. Gehring, Mansfield, \$19,910; J. B. Zimora, Cincinnati, \$18,675; F. J. Zimmerman, Springfield, \$18,100; C. E. Pilkington, Gambler, \$17,600; A. D. Sizoo, Akron, \$16,845; E. H. Hebbelby, Tiffin, \$16,200; H. W. and Robinson, Coshocton, \$16,000; T. C. Lutz, Urbana, \$15,145; A. M. Koch, St. Marys, \$14,725; H. D. Moore, McConnelsville, \$14,000; D. K. Korn, Plain City, \$13,400; H. Stewart, Chillicothe, \$13,400; F. M. Langley, Chillicothe, \$12,350; E. R. Hayes, Akron, \$11,410; M. A. Head, New, Columbus, \$11,426; and W. C. Kline, Euclid, \$11,100.

Principal Wilson Is Ordered To Bed

Washington, July 21.—President Wilson was ordered to bed today following his work on the McPherson flu. He is suffering from the grippe.

WEATHER The weather was clear and warm at the time of the deluge. The wind was from the west and the temperature was in the upper 70s. The rain fell in a steady shower for several hours, beginning about 8 o'clock and continuing until about 11 o'clock. The total rainfall was about 1.5 inches.

MURPHY VOTES FOR REPEAL OF DAYLIGHT BILL

Washington, D. C., July 21.—The President was adversely 20, of which with the aid of the agricultural bill, and later to pass the bill over the President's veto. The vote was 20-10. The bill was introduced by Mr. Murphy of the 18th Ohio District, in voting for the repeal of the daylight saving law. The bill was introduced by Mr. Murphy of the 18th Ohio District, in voting for the repeal of the daylight saving law. The bill was introduced by Mr. Murphy of the 18th Ohio District, in voting for the repeal of the daylight saving law.

War Of Revenge Impossible Says Von Bernstorff

Berlin, July 21.—"Everybody living in Germany knows that we never would undertake a war of revenge," declared Count Von Bernstorff, former German ambassador to the United States, in an address here this afternoon. Count Von Bernstorff also warned against speculating on a war between America and Japan, which he said "is a mistake often made in Germany here." This speculation, added Bernstorff, would revive Germany's old reputation as a nation of diplomats. He said that the present situation is a conflict, the fiercest and most serious, which has ever been known since the world war. He said that the present situation is a conflict, the fiercest and most serious, which has ever been known since the world war.

Claims Italians And Rumanians Complete Treaty

London, July 21.—Mr. Lybch, representative of the Daily Express, telegraphed today that he had learned that the Italian and Rumanian governments have concluded a secret treaty aimed against the Axis. Slavs unknown to the peace conference in Paris.

Forest Fires In North Michigan

Detroit, July 21.—Forest fire activity in the North part of Michigan with greater fury than there a few weeks ago, which did millions of dollars worth of damage before they were checked by rain. Forest fires are still burning in several places, and many towns, in the upper and lower parts of the state, are threatened.

Wine Wager And Falls Down Dead

Cedar Point, Ohio, July 21.—Winning a wager that he could swallow a ball of wax, machine on Forty-first street, saved property in that vicinity by dislodging the drift wood.

Old Slave Leaves Fortune

Fayette, Mo., July 21.—Jackson Hill an aged negro, former slave who died here recently, left an estate valued at more than \$100,000.

WEEGEE CREEK VALLEY FLOOD SWEEPED BEFORE

It was almost 23 years to a day from the awful catastrophe of last Friday night, that Weegee creek first overflowed its banks to a depth of 30 feet and swept everything before it. The water came up so fast that loss of life in the first flood was not great, but the that followed was due only to the fact that the creek valley was not nearly so high as it is at the present time. Three were drowned in the flood of 23 years ago, consisting of a man, his wife and child. They resided in the valley of the creek and the water came up so fast that they were caught unawares. Their bodies were never recovered. Corpses in the creek valley at that time were buried and the damage totaled thousands of dollars.

Flood Loss In Creek Valleys Locally, Heavy

The flood loss along the McPherson creek valley is heavy. Practically all of the crops in the lowlands as well as those on the neighboring hill sides were destroyed. Corn was laid to the ground, and in many instances the trees were entirely uprooted. Through Belmont McPherson creek ran like the Ohio river at a flood stage. With the exception of a few trees and a few crops, the rest of the crops were washed away. Among the losses which were whirled away in the torrent were the stern wheel gasoline boats owned by Grant and Joe Anderson, a total loss of about \$3000. The current was so strong that the waters from the McPherson creek valley were tossed on the West Virginia shore, and the trees hooked up at least ten feet in the local pool.

Wine Wager And Falls Down Dead

Cedar Point, Ohio, July 21.—Winning a wager that he could swallow a ball of wax, machine on Forty-first street, saved property in that vicinity by dislodging the drift wood.

Old Slave Leaves Fortune

Fayette, Mo., July 21.—Jackson Hill an aged negro, former slave who died here recently, left an estate valued at more than \$100,000.

WEBB SPUR OF PENNSYLVANIA RAILROAD PRACTICALLY WIPED OUT; WEBB COAL MINE ESCAPES

Officials of the Pennsylvania Railroad Company estimate the loss incurred to the Webb spur by the flood Saturday night at \$200,000. Four miles of track were completely washed away and five bridges wrecked, while the main road, in some places was completely torn up. The railroad company now has a force of 200 men working night and day to repair the damage. The track, as well as all the bridges, were practically wiped out. It will be at least two weeks before trains can run over the tracks. An official of the railroad company in an interview here today said: "We are doing everything possible to expedite the work however, but it will be at least two weeks before trains can run over the tracks." "It will be at least two weeks before trains can run over the tracks." "It will be at least two weeks before trains can run over the tracks."

The Webb spur of the Pennsylvania Railroad, the largest in the Eastern Ohio field. It was not damaged much by the deluge but, of course, to remain idle on account of the damage to the railroad men are employed there and several hundred men with the section gang that is repairing the track. The section of the tracks damaged between the Tunnel and McPherson, a total stretch of about 4 miles, is completely washed out and a shuttle train along the boundaries of the Webb company. The section of the tracks of the Webb company, containing an engine and 10 loaded cars, was washed out. The train was just pulling out when struck by the flood and later occupied a temporary island in the middle of the flooded waters. It will be required to remain in that position until it is hauled to that point. Officials of the Cambria Coal Company, owners of the Webb mine, are rather skeptical about the railroad company being able to repair the tracks within two weeks. "I don't think they can do it in less than a month," he said. "If they finish this morning, we're not for the damage done to the mine, we would be able to go on tomorrow," he said.

FLOOD DAMAGE TO THE O. R. & W. WILL RUN INTO THE HUNDREDS OF THOUSANDS; TRAINS STOPPED

TWO WEEKS BEFORE TRAFFIC CAN BE RESUMED, IT IS BELIEVED. NINE BRIDGES AND FOUR MILES OF TRACK ARE WASHED AWAY. Never since the construction of the O. R. & W. railroad from Bell to Woodfield, has it experienced such damage as was suffered by the section along Weegee creek and Captin's Saturday evening. The damage to the O. R. & W. line alone will amount to several hundred thousand dollars, while the personal damage to buildings and crops along these streams will increase the aggregate to upward of a million dollars or more. At the office of the O. R. & W. this morning Agent Turner stated that it would be two weeks before any train could be operated upon the entire division of the system, which means between Belmont and Woodfield. The western end of the line from Woodfield to Zanesville suffered no loss, and trains will run as far as Woodfield as usual. The local division suffered the loss of nine bridges, four of these were on what is known as the Rockyford section, between Captin and Kellerman. Captin creek, the remaining two being along Weegee creek. In addition to the over three miles of track were washed out. The O. R. & W. track crew started work Sunday morning on the first bridge near the mouth of Weegee creek, and a force of men are at work on the nearby bridge, the Rockyford bridge. The second bridge, the Rockyford bridge, is being repaired.

Agent Turner went to Webb this morning to engage 600 laborers for that point. It is believed that he will be able to secure plenty of labor at that point. Back in July, 1904, Weegee creek suffered a similar flood, and it is said that there was more damage at that time, with the damage done was inconceivable as compared to that wrought by the present deluge. By reason of the washout of the track, it will be unable to deliver coal to Captin, Kellerman, Zanesville, Bell, and Allandale by express and by mail. The O. R. & W. will be unable to deliver coal to Captin, Kellerman, Zanesville, Bell, and Allandale by express and by mail. The O. R. & W. will be unable to deliver coal to Captin, Kellerman, Zanesville, Bell, and Allandale by express and by mail.

Figure 10.—Photoreproduction of front page of Bellaire Daily Leader for Monday, July 21, 1919.

Flood of 1919

"NINE LIVES AND PROPERTY LOSS ESTIMATED AT MILLION IS TOLL OF FLOOD IN THE VALLEY OF WEGEE CREEK"

"PARTIES CONTINUE SEARCH FOR BODIES OF THOSE WHO DROWNED IN DELUGE OF SATURDAY NIGHT"

Nine lives and property loss totalling a million dollars is the toll of the storm which swept Eastern Ohio Saturday afternoon and evening. On Wegee Creek at Mapleton, just one half mile above the Webb mine two houses were swept away and the inhabitants * * * were drowned.

According to a story related to a Leader Reporter by Moxie Steve, a member of the deceased family, the storm at Mapleton was practically a cloud burst * * * He stated yesterday that the run, a tributary to Wegee Creek, began to rise shortly after the rain struck Webb. It was a raging torrent inside of fifteen minutes and suddenly a wall of water at least fifteen feet high swept down the valley carrying everything before it. * * *

"FLOOD DAMAGE TO THE OR&W WILL RUN INTO THE HUNDREDS OF THOUSANDS; TRAINS STOPPED"

Two weeks before traffic can be resumed it is believed. Nine bridges and four miles of track are washed away. Never since the construction of the OR&W railroad from Bellaire to Woodsfield, has it experienced such damage as was incurred by the storm along Wegee Creek and Captina Saturday evening. The damage to the OR&W line alone will amount to several hundred thousand dollars, while the personal damage to buildings and crops along these streams will increase the aggregate damage to upward of a million dollars or more. * * *

"WEBB SPUR OF PENNSYLVANIA RAILROAD PRACTICALLY WIPED OUT; WEBB COAL MINE ESCAPES." * * *

"FLOOD LOSS IN CREEK VALLEYS LOCALLY HEAVY"

The flood loss along the McMahan Creek valley is heavy. Practically all of the crops in the lowlands as well as those on the neighboring hillsides were destroyed. Corn was laid to the ground, and in many instances the crops were entirely washed away. Through Bellaire McMahan's Creek ran like the Ohio River at a flood stage.

(Bellaire Daily Leader, 1919)

Miss Kirkland mentions another flood of the 1930's:

When I was a child, I remember a flash flood which occurred on Wheeling Creek in Blaine and Barton near Bridgeport, Ohio. Flood waters covered old Route 40 and surrounding land in that area. We were in St. Clairsville visiting my aunt and uncle when it happened. We all went down to see the flood.