



Figure 15b. Borehole geophysical logs of test hole 6 (Sh:V-78) and hydrogeologic units of the shallow aquifer system northeast of the erosional scarp at Naval Support Activity Memphis, Millington, Tennessee.