



EXPLANATION

- Gullied channel showing active erosion
- ..... Stable channel with sandy bottom
- - - - - Stable channel with grass bottom
- Active headcut in channel
- Average land slope, in percent



MAP OF LOGAN DRAW BASIN ABOVE RONGIS RESERVOIR IN WYOMING, SHOWING AVERAGE LAND SLOPES AND STATUS OF CHANNEL EROSION

1 0 1 Mile