


Well and spring numbers above bar; depth of well and water-bearing rocks below bar

Abnormally high nitrate, total hardness low
Sulfate above average, total dissolved solids generally high


WATER-BEARING ROCKS

- M Mantle material
- SI St. Louis limestone
- Wa Warsaw limestone
- Fp Fort Payne chert
- Cg Chattanooga shale
- Se Sellersburg limestone
- Lo Louisville limestone

CHEMICAL ANALYSIS



Nitrate is shown when more than 10 parts per million or 0.161 equivalents



MAP OF SCOTTSVILLE AREA, KENTUCKY, SHOWING CHEMICAL ANALYSES AND SOURCES OF WATER

